

APPENDIX C: SITE PHOTOGRAPHS TAKEN ON 29 JANUARY 2025



Figure 1: Looking northwest across the southeastern portion of the site. Arrow indicating existing dam wall.



Figure 2: The land to the southeast and east of the existing dam. Arrow indicating existing dam wall.



Figure 3: Looking west towards the pumpstation and southern section of the dam wall. Pump station marked by yellow arrow.



Figure 4: Downstream of the dam wall.



Figure 5: The pumpstation below the dam wall.



Figure 6: The dam embankment which will be increased to accommodate the expansion.



Figure 7: The existing dam - the western portion of the dam site.



Figure 8: Looking east across the dam.



Figure 9: The farm road to the west of the dam. This road will be inundated by the larger dam.



Figure 10: The fallow agricultural land that will be lost by the proposed expansion.



Figure 11: The area where the new enlarged dam will be expanded.



Figure 12: Looking south across the dam.



Figure 13: The northern portion of the dam basin.



Figure 14: Orchards that will be lost as a result of the expansion.



Figure 15: Looking south from upstream point of dam.



Figure 16: The non-perennial watercourse before it enters the dam.



Figure 17: Looking south across the eastern portion of the dam.



Figure 18: This shed may be affected by the new enlarged dam basin.



Figure 19: Looking west across the northern portion of the dam basin.



Figure 20: The piped section of the watercourse entering the dam.



Figure 21: Disturbed land between Dam 1 and Dam 2. Dam 2 wall is indicated with an arrow.

PHOTOGRAPHS TAKEN BY TONI BELCHER



Views of the Modderas Stream upstream (top and centre) and downstream (bottom) of the dam



Views of the Modderas Dam (top) and the Alternative Dam 2 (middle) as well as the tributary of the Modderas River near Dam 2(bottom)

PHOTOGRAPH DIRECTIONS

